

## Cleaning recommendation for powder-coated surfaces

The cleaning of powder-coated surfaces should be done **generally first with a soft dry cloth**.

If pollution cannot be removed in this kind, the cloth can be **moistened** and also if necessary there **can be used a ph-neutral cleaner**.

**Basically** there have to be avoided any **contact between the powder coatings and alkaline or acid substances**. In this case especially the metallic powders show a high sensitive reaction.

If the usage of a **special cleaner** is necessary to eliminate certain pollutions we recommend to **check the applicability of the cleaner at a hidden place first**.

We do not guarantee for damages which are caused by incorrect cleaning.  
Exceptions require previous verifications.